

LOCATIONS VISITED ON 12/28/2010, Random Checks														
LEASE#	Case	CASE#	OPERATOR	WELL NAME	WELL #	API#2	TWP	RGE	SEC	QTR	INS 1	INS A	OPENED	CLOSED
NMSF079634	L	NMSF079634	BURLINGTON RESOURCES O&G CO L	MC CLANAHAN	5Y	300452134800S	28N	10W	13	SWNW	ES	SA	10/03/03	10/08/03
NMSF079634	L	NMSF079634	BURLINGTON RESOURCES O&G CO L	MC CLANAHAN	5Y	300452134800S	28N	10W	13	SWNW	ES	SA	12/17/09	01/04/10
NMSF077085	L	NMSF077085	CONOCOPHILLIPS COMPANY	OMLER	7	300450714900S	28N	10W	26	NWSE	ES	SA	10/08/03	10/13/03
NMSF077085	L	NMSF077085	CONOCOPHILLIPS COMPANY	OMLER	7	300450714900S	28N	10W	26	NWSE	ES	SA	12/16/09	
NMSF077085	L	NMSF077085	CONOCOPHILLIPS COMPANY	OMLER	7	300450714900S	28N	10W	26	NWSE	ES	SA	07/28/10	07/28/10
NMSF077085	L	NMSF077085	BURLINGTON RESOURCES O&G CO L	OMLER	1	300450700500S	28N	10W	36	NWSW	ES	SA	10/08/03	10/13/03
NMSF077085	L	NMSF077085	BURLINGTON RESOURCES O&G CO L	OMLER	1	300450700500S	28N	10W	36	NWSW	ES	SA	12/16/09	01/04/10
NMNM04209	L	NMNM04209	CONOCOPHILLIPS COMPANY	FEUILLE FEDERAL	2	300450716400s	28N	9W	26	SENE	ES	SA	12/08/04	12/08/04

STATUS	Rmk Te		
P+A	Location looks good. Access road not bermed. Set of tracks thru location.		
P+A	70% Coverage fan accepted.		
ABD	Access road not bermed or reseeded. Berm around location needs to be knocked down. Location needs to be reseeded. Location is overgrown with tumbleweeds		
ABD	Needs access road closed and bum every 100 feet an it all needs reseeded and ripped, silt trap in the SE corner of pad slop pull back into pad.		
ABD	Work was done and looks good. Fan Accepted		
P+A	Road thru location needs to be bermed, ripped, and reseeded. Cement and electrical cables around dryhole hole marker need to be removed.		
P+A	Twinned on the Omler #501well pad Fan accepted.		
ABD	This abandoned location was inspected for surface compliance due to the lack of Gold Book standards for rehab. All that has happened to the site is the equip		

eds.
ment removed. No reclamation has occurred on the location.