



Santo Domingo Pueblo Head Start and Early Head Start Complex

TIF Project Funding: \$115,000
Awarded 2010

9/21/10- Earthwork



9/28/10- Architectural review
of foundation review



North wall foundations



Sewage treatment system



EHS wing slab prep



Kitchen plumbing rough-in



Grease trap



Overview from entry drive



South entry to EHS wing (to playground)



South wall of HS wing



HS wing framing



Head Start Classroom



Infant Classroom



Classroom Activity Center



Entry to EHS (Early Head Start) hallway



Building utilities in kitchen



Sheetrock in 3 year old classroom



View from entry drive



Entry



Entry Canopy



Bus Shelters



Rooftop HVAC units delivered to site



Roofing at HS (Head Start) wing



Roof on HS wing



The roofing is improving with warmer weather



Curb and gutter along service drive



Curbing at exit drive



Entry Drive



HS Classroom



HS Corridor



Head Start classroom



Lobby and Dining Areas



4 year old classroom



EHS Classroom- crib area



Partial kitchen equipment installation



Lobby Skylight



Mechanical Room



Curb at bus drop off



Main Entrance



Much to be removed



Head Start Playground



Parking lot drainage issue



Stockpiled mulch- Forest fire smoke in background



Completed Head Start Classroom



Infant classroom furnishings being installed



Completed Infant Room



Library furnishings being installed



HS finishings being installed



Dining room finishings being installed



Completed Head Start Corridor



Completed Lobby/Reception