

Albuquerque Area Master Plan: Facility Condition Assessments



Albuquerque Area Master Plan: Facility Condition Assessments



Exterior Findings

- ADA Compliance
- Damaged asphalt and concrete paving
- Worn and damaged exterior wall finishes
- Faded parking lot pavement markings
- Building envelope improvements:
 - Exterior wall repairs
 - Window and door upgrades

Albuquerque Area Master Plan: Facility Condition Assessments



Interior Findings

- ADA Compliance
 - Restrooms
 - Door hardware
 - Room identification signs
- Damaged and outdated finishes
- HVAC improvements
- Safety and Security
 - Fire alarm system upgrades
 - Fire suppression system upgrades