




Report for 2013 HM 1 and SM 11 Wildlife-Vehicle Collision Mitigation





I-25 at Raton (Mileposts 450-454)

Proposed Treatment: Wildlife fencing connected to culverts for wildlife underpasses, escape ramps, and flashing lights/signs to warn drivers




U.S. 70 East of Alamogordo (Mileposts 236-242)

Proposed Treatment: Wildlife crossing signs with seasonal flashing lights to warn drivers



U.S. 550 North of Cuba (Mileposts 65-80)

Proposed Treatment: Wildlife crossing signs with night-time flashing lights to warn drivers



Example Warning Sign



View from U.S. 550 looking east